HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ELLIS ISLAND, CONTAGIOUS DISEASE HOSPITAL OFFICE HABS NY-6086-M

BUILDING

(Ellis Island, Nurses' Quarters)

Statue of Liberty National Monument

New York Harbor

New York

New York County

New York

INDEX TO BLACK AND WHITE PHOTOGRAPHS

James W. Rosenthal, photographer, October 2009

| NY-6086-M-1 | Perspective view from northeast |
|--------------|--|
| NY-6086-M-2 | Perspective view from northwest |
| NY-6086-M-3 | Elevation of north facade with scale |
| NY-6086-M-4 | Perpective view of north portico from northeast |
| NY-6086-M-5 | Elevation of east facade with scale |
| NY-6086-M-6 | Perspective view with south corridor from southeast |
| NY-6086-M-7 | View of south entrance from south corridor |
| NY-6086-M-8 | View of south corridor from north looking towards corridor C9A |
| NY-6086-M-9 | View of north entrance |
| NY-6086-M-10 | View of stair hall from north |
| NY-6086-M-11 | Perspective view of stair from northwest |
| NY-6086-M-12 | View of south bathroom on first floor |
| NY-6086-M-13 | View of northeast room on first floor from northwest |
| NY-6086-M-14 | Detail view of sconce in northwest room on first floor |
| NY-6086-M-15 | View of northwest room on first floor from northwest |
| NY-6086-M-16 | View of southwest room on first floor from east |

ELLIS ISLAND, CONTAGIOUS DISEASE HOSPITAL OFFICE HABS NY-6086-M INDEX TO PHOTOGRAPHS

| NY-6086-M-17 | Perspective view of fireplace in northwest rooom of first floor |
|--------------|---|
| NY-6086-M-18 | View o washroom in southwest room on first floor |
| NY-6086-M-19 | View of second floor landing from south |
| NY-6086-M-20 | View of second floor north restroom from south |
| NY-6086-M-21 | View of northeast room on second floor from stair hall |
| NY-6086-M-22 | Detail view of workbench and gas spigots in northeast room second floor |
| NY-6086-M-23 | View of northwest room on second floor from southeast |
| NY-6086-M-24 | View of southeast room on second floor from northeast |
| NY-6086-M-25 | View of southwest room on second floor from north |
| NY-6086-M-26 | View of storage closet in southwest room on second floor |
| NY-6086-M-27 | View of attic from south |
| NY-6086-M-28 | Detail view of dormer window in attic |